



### 1. Color differentiation of ultrasonic sensors

Ultrasonic sensors should be color differentiated. It has to be taken into account, that the surface is very glossy. For this purpose a color sensor type **SPECTRO-3-50-POL** is used at a distance of approximately 42mm to the ultrasonic sensor surface. The detecting area at this distance is around 18mm. The ultrasonic sensors can be proper distinguished as shown in the screen shots.

