



1. Differentiation of zinc plated steel parts and raw steel parts

Zinc plated steel turned parts should be differentiated from raw steel parts. For this purpose a color sensor type **SPECTRO-3-30-POL** is used. The distance of the sensor to the object is approximately 15mm. A proper differentiation is possible as shown in the screen shots.

